

Check Out



+44 02071013975

Bookings@wilsoninventories.co.uk

Prepared on behalf of Paramount Properties

Property inspected by James Wilson

Address

Example
Check-out
Report

Carried Out

April
3rd 2025



Contents

| | |
|-----------------------------|----|
| Disclaimers | 2 |
| Areas | 3 |
| SCHEDULE OF CONDITION | 3 |
| CLEANING SUMMARY | 4 |
| METRE READINGS | 5 |
| KEY SETS | 6 |
| SMOKE AND CO2 ALARMS | 7 |
| ENTRANCE & HALLWAY | 8 |
| KITCHEN | 11 |
| RECEPTION | 19 |
| INNER HALLWAY | 24 |
| BATHROOM | 26 |
| BEDROOM ONE | 32 |
| BEDROOM TWO | 38 |
| BEDROOM THREE | 43 |
| EN-SUITE | 49 |
| GARDEN | 55 |
| PROPERTY COMPLIANCE | 57 |
| Actions | 58 |
| Declaration | 59 |

Disclaimers

1. WILSON INVENTORIES SERVICES covers the property only to the extent that the condition of the premises permits. It only extends to the parts of the premises that are readily accessible. All other parts of the premises i.e. attics, garages, lofts and communal areas that are not relevant to the inventory, are specifically excluded.
2. This document is considered to be an accurate assessment of the contents and condition of the property. You have 14 days from the date of this report to notify us in writing of any amendments you wish to make. These should be sent to james@wilsoninventories.co.uk. If no amendments are received within this time you are deemed to have agreed with the contents of this report. Amendments will only be made to the report with all parties' agreement. It is the responsibility of the Landlord and Tenant to agree to amendments prior to sending any request to WI.
3. Unless the Inventory is carried out in daylight hours, the exterior and belongings will not have been inspected.
4. If a garden needs inspecting WI will endeavour to mention plants and shrubs however WI considers plants to be perishable.
5. Lighting, electrical appliances, machinery and other similar items will be tested where practical, and in any event for power supply only. Burglar alarms and panic alarms are not tested.
6. Carpets, rugs and other floor coverings have been inspected to the extent that they are sufficiently clean so that stains and markings, including burns and other damage can be readily identified.
7. Unless otherwise stated in writing, items in boxes, plastic sacks and other containers are assumed to be awaiting removal and are specifically excluded from the inventory.
8. All items are described only so that they can be identified. Sizes of objects are given only as approximate and are purely an aid for identification.
9. It should be noted that the compiler of this report is not an expert in fabrics, woods, materials, antiques, etc and not a qualified surveyor. This inventory should not in any way be used as a report for valuation purposes for the premises and its contents or as a structural survey report.
10. Every effort has been made to carefully check the property and its contents, however, WI representative cannot move extremely heavy Contents, nor can we undertake to attempt entry to inaccessible places. Our clerks will not report on areas such as overcrowded drawers & cupboards.
11. The WI representative is not aware of recently bought items. New is only stated if the item is still within packaging. This inventory has been compiled on the basis that, unless otherwise stated, an item is free from visible soiling, defects or damage.
12. Newspapers, magazines, perishables, houseplants are not included unless specifically requested. Books, compact discs, DVDs, videotapes and other similar items will not be listed individually but will be stated as 'collections'.
13. Properties containing large amounts of assorted crockery, cutlery, glasses etc will not have items listed individually but will be listed as "assorted items".
14. The person preparing the Inventory is not an expert in The Fire and Safety Regulations in relation to soft furnishings. It assumes that all furnishings & fabrics have been checked by the landlord and/or managing agent to ensure they comply with the relevant regulations at date of compilation.
15. Any Inventories compiled with the tenants in situ may contain inaccuracies for which we cannot be held responsible.
16. Smoke alarms will be listed on the inventory but will only be tested for sound in accordance with the legislation of October 2015 and only where practically possible to do so. Liability for ensuring the property complies with the legislation remains with the Landlord.
17. Meter readings can only be taken if meters are accessible and clearly marked. Otherwise the reading must be taken by the relevant boards.
18. It is essential that all items are returned to respective rooms as listed on the original Inventory before the Check Out is due to be carried out. Where items have not been returned to their original position and are not easily seen they may be noted as "Not Seen" on the Check Out and their replacement may be charged for.
19. All personal items should be removed prior to the Check Out and the tenant should be ready to vacate the property at the end of the Check Out returning all sets of keys.
20. Unless otherwise stated, the report was carried out at the date and time stated on the front cover and all photos were taken during the inspection.
21. Blinds in the premises are visually checked. We are unable to verify that the blinds comply with child safety requirements of BS EN 13120:2009 + A1:2014 placed on the manufacturer, supplier and professional installation of internal window blinds.

1. SCHEDULE OF CONDITION

| Ref | Name | Condition |
|------|-----------------------|--|
| 1.1 | Decorative Order | General good decorative order Few loose door handles |
| 1.2 | Ceilings | General good condition Few scuff marks |
| 1.3 | Lights | All working |
| 1.4 | Walls | Few scuff marks and shading |
| 1.5 | Windows & Sills | Generally good, functional order Few light marks to sills |
| 1.6 | Curtains / Blinds | Minor paint marks, scuffs and light shading Creasing and fraying to blind edges |
| 1.7 | Woodwork | Good condition throughout |
| 1.8 | Flooring | Scratches and scrapes Aged floorboards |
| 1.9 | Kitchen & Appliances | Minor food debris to interior of draws Most appliances clean and tested |
| 1.10 | Bathroom & Appliances | In clean condition Toilet roll holder loose to main bathroom |
| 1.11 | Contents | Mattresses seen clean Slight wear to sofa and wooden contents |

2. CLEANING SUMMARY

| Ref | Name | Condition |
|-----|-----------------------|----------------|
| 2.1 | General Cleanliness | Domestic clean |
| 2.2 | Carpets & Flooring | Domestic clean |
| 2.3 | Windows & Sills | Domestic clean |
| 2.4 | Kitchen & Appliances | Domestic clean |
| 2.5 | Bathroom & Appliances | Domestic clean |
| 2.6 | Contents | Domestic clean |

3. METRE READINGS

| Ref | Name | Description | Reading |
|-----|----------------|---|---------|
| 3.1 | Gas Meter | Location: Side alleyway to building Serial Number: E6S02498881756 | 13323 |
| 3.2 | Electric Meter | Location: Communal hallway cupboard, FB2 key required Serial Number: Z17QK32219 | 27921 |



Ref #3.1



Ref #3.2

4. KEY SETS

| Ref | Name | Description |
|-----|----------|---|
| 4.1 | Key sets | 1x management set 1x chrome Chubb key 5x chrome Yale types 2x tenant sets provided All three sets returned to agent |



Ref #4.1



Ref #4.1

5. SMOKE AND CO2 ALARMS

| Ref | Name | Location Room & Floor | Test Result |
|-----|------------------------|---|---------------------|
| 5.1 | Smoke Alarms | Floor: 1 level Location: Entry hallway | Audible sound heard |
| 5.2 | Heat Sensor Alarms | Floor: 1 level Location: Kitchen | Audible sound heard |
| 5.3 | Carbon Monoxide Alarms | Floor: 1 level Location: Kitchen | Audible sound heard |



Ref #5.1



Ref #5.2



Ref #5.3


6. ENTRANCE & HALLWAY




Ref #6



Ref #6



Ref #6



Ref #6

| Ref | Name | Condition |
|-----|------------------|--|
| 6.1 | Door & Frame | As per inventory + Minor chip to mid left frame Light scuffing to high level frame |
| 6.2 | Door Fixtures | As per inventory |
| 6.3 | Ceiling | As per inventory |
| 6.4 | Lighting | As per inventory + Good, working order |
| 6.5 | Walls | As per inventory + Scuffing, heavier to left wall Chippings to angle |
| 6.6 | Skirting | As per inventory + Minor shading and scuffing |
| 6.7 | Switch / Sockets | As per inventory |
| 6.8 | Heating | As per inventory |

6. ENTRANCE & HALLWAY (CONT.)

| Ref | Name | Condition |
|------|------------------|---|
| 6.9 | Flooring | As per inventory + Black spot mark to coir carpet Minor debris |
| 6.10 | Built-In-Storage | As per inventory + Faint scuff to exterior Loose pull to door Scuffing to interior shelf |

Contents

| | | |
|------|------------|------------------|
| 6.11 | Fuse boxes | As per inventory |
| 6.12 | Telecom | As per inventory |
| 6.13 | Pad ADT | As per inventory |

Cleanliness

| | | |
|------|-------------|----------------|
| 6.14 | Cleanliness | Domestic clean |
|------|-------------|----------------|



Ref #6.1



Ref #6.1



Ref #6.1



Ref #6.3




Ref #6.4



Ref #6.5

6. ENTRANCE & HALLWAY (CONT.)

| Ref | Name | Condition |
|---|-----------|---|
|  | |  |
|  | | |
| 03 Apr 2025 12:13 | Ref #6.6 | 03 Apr 2025 12:13 |
| 03 Apr 2025 12:13 | Ref #6.9 | 03 Apr 2025 12:13 |
| Ref #6.9 | | |
|  | |  |
| 03 Apr 2025 12:15 | Ref #6.10 | 03 Apr 2025 12:15 |
| 03 Apr 2025 12:15 | Ref #6.10 | 03 Apr 2025 12:15 |
| Ref #6.10 | | |
|  | |  |
| 03 Apr 2025 12:26 | Ref #6.10 | 03 Apr 2025 12:26 |
| 03 Apr 2025 12:26 | Ref #6.10 | 03 Apr 2025 12:26 |
| Ref #6.10 | | |
|  | | |
| 03 Apr 2025 12:16 | Ref #6.11 | 03 Apr 2025 12:16 |
| 03 Apr 2025 12:16 | Ref #6.11 | 03 Apr 2025 12:16 |
| Ref #6.11 | | |
|  | |  |
| 03 Apr 2025 12:16 | Ref #6.12 | 03 Apr 2025 12:16 |
| 03 Apr 2025 12:16 | Ref #6.13 | 03 Apr 2025 12:16 |
| Ref #6.12 | | |


7. KITCHEN




Ref #7



Ref #7



Ref #7



Ref #7


| Ref | Name | Condition |
|-----|------------------|---|
| 7.1 | Ceiling | As per inventory |
| 7.2 | Lighting | As per inventory + Extra bulbs left by tenant |
| 7.3 | Walls | As per inventory + Stain marks and scratches |
| 7.4 | Skirting | As per inventory + Few indented scrapes Brown staining next to fridge Review - Investigate |
| 7.5 | Windows & Sills | As per inventory |
| 7.6 | Switch / Sockets | As per inventory |
| 7.7 | Heating | As per inventory + Few marks to edges |
| 7.8 | Flooring | As per inventory + Light water stains under table |

| 7. KITCHEN (CONT.) | | |
|--------------------|------------------|---|
| Ref | Name | Condition |
| 7.9 | Kitchen Units | As per inventory + Few light stains ; Food debris to interior of draws Review - Investigate |
| 7.10 | Worktops | As per inventory + Black shading to sealant behind sink |
| Kitchen Appliances | | |
| 7.11 | Sink | As per inventory + Scratches to interior Clean |
| 7.12 | Extractor Hood | As per inventory + Few light stain marks Good, physical condition |
| 7.13 | Hob | As per inventory |
| 7.14 | Oven & microwave | As per inventory + Moderate burnt on staining to baking tray Review - Investigate |
| 7.15 | Dishwasher | As per inventory |
| 7.16 | Fridge / Freezer | As per inventory + Minor stain or food debris |
| 7.17 | Boiler | As per inventory |
| Contents | | |
| 7.18 | Table and chairs | As per inventory + Wear, debris and ring marks to top of table Marks and wear to chairs |
| 7.19 | Bin | As per inventory + Minor rusting and marks Contents to interior |
| 7.20 | Miscellaneous | As per inventory |
| Cleanliness | | |
| 7.21 | Cleanliness | Domestic clean |

7. KITCHEN (CONT.)

| Ref | Name | Condition |
|---|-------------------|-----------|
|  | 03 Apr 2025 13:25 | Ref #7.1 |
|  | 03 Apr 2025 13:25 | Ref #7.2 |
|  | 03 Apr 2025 13:25 | Ref #7.2 |
|  | 03 Apr 2025 13:26 | Ref #7.3 |
|  | 03 Apr 2025 13:26 | Ref #7.3 |
|  | 03 Apr 2025 13:28 | Ref #7.3 |
|  | 03 Apr 2025 13:28 | Ref #7.3 |
|  | 03 Apr 2025 13:47 | Ref #7.3 |
|  | 03 Apr 2025 13:29 | Ref #7.4 |
|  | 03 Apr 2025 13:46 | Ref #7.4 |
|  | 03 Apr 2025 13:30 | Ref #7.5 |
|  | 03 Apr 2025 13:30 | Ref #7.5 |


7. KITCHEN (CONT.)

| Ref | Name | Condition |
|---|-------------------|-----------|
|  | 03 Apr 2025 13:31 | Ref #7.6 |
|  | 03 Apr 2025 13:33 | Ref #7.7 |
|  | 03 Apr 2025 13:33 | Ref #7.8 |
|  | 03 Apr 2025 13:33 | Ref #7.8 |
|  | 03 Apr 2025 13:33 | Ref #7.8 |
|  | 03 Apr 2025 13:33 | Ref #7.8 |
|  | 03 Apr 2025 13:36 | Ref #7.9 |
|  | 03 Apr 2025 13:39 | Ref #7.9 |
|  | 03 Apr 2025 13:40 | Ref #7.9 |
|  | 03 Apr 2025 13:40 | Ref #7.9 |
|  | 03 Apr 2025 13:40 | Ref #7.10 |
|  | 03 Apr 2025 13:40 | Ref #7.10 |

7. KITCHEN (CONT.)

| Ref | Name | Condition |
|---|------|---|
|  | |  |
|  | |  |
|  | |  |
|  | |  |
|  | |  |
|  | |  |
|  | | |

7. KITCHEN (CONT.)

| Ref | Name | Condition |
|---|------|---|
|  | | |
| | |  |
| | |  |
|  | | |
| | |  |
| | |  |
|  | | |
| | |  |
| | |  |
|  | | |
| | |  |
| | |  |

7. KITCHEN (CONT.)

| Ref | Name | Condition |
|---|-----------|---|
|  | |  |
|  | | |
| | Ref #7.18 | 03 Apr 2025 13:45 |
| | Ref #7.18 | 03 Apr 2025 13:45 |
| | Ref #7.18 | 03 Apr 2025 13:45 |
|  | |  |
| | Ref #7.18 | 03 Apr 2025 13:45 |
| | Ref #7.18 | 03 Apr 2025 13:45 |
| | Ref #7.18 | 03 Apr 2025 13:45 |
|  | |  |
| | Ref #7.18 | 03 Apr 2025 13:45 |
| | Ref #7.19 | 03 Apr 2025 13:46 |
| | Ref #7.19 | 03 Apr 2025 13:46 |
|  | |  |
| | Ref #7.19 | 03 Apr 2025 13:46 |
| | Ref #7.20 | 03 Apr 2025 13:48 |
| | Ref #7.20 | 03 Apr 2025 13:48 |

7. KITCHEN (CONT.)

| Ref | Name | Condition |
|---|-----------|-------------------|
|  | | |
| | | 03 Apr 2025 13:48 |
| | Ref #7.20 | |
|  | | |
| | | 03 Apr 2025 13:48 |
| | Ref #7.20 | |
|  | | |
| | | 03 Apr 2025 13:48 |
| | Ref #7.20 | |
|  | | |
| | | 03 Apr 2025 13:48 |
| | Ref #7.20 | |
|  | | |
| | | 03 Apr 2025 13:48 |
| | Ref #7.20 | |


8. RECEPTION




Ref #8



Ref #8



Ref #8



Ref #8

| Ref | Name | Condition |
|-----|---------------|--|
| 8.1 | Door & Frame | As per inventory + Minor scuff and odd marks to door Chips to door edges |
| 8.2 | Door Fixtures | As per inventory |
| 8.3 | Ceiling | As per inventory |
| 8.4 | Lighting | As per inventory + Good, working order |
| 8.5 | Walls | As per inventory |
| 8.6 | Fireplace | As per inventory + Scuff to top of mantel Scratches to hearth |
| 8.7 | Skirting | As per inventory + Black scuff marks right side |

8. RECEPTION (CONT.)

| Ref | Name | Condition |
|------|-------------------|--|
| 8.8 | Windows & Sill | As per inventory + Tenant applied tape to window surround to stop draft Black mark to right side sill edge Orange drip staining under window Review - Investigate |
| 8.9 | Blinds / Curtains | As per inventory + Moderate pink mark to reverse of left curtain Moderate drip stains to right side curtain Review - Investigate |
| 8.10 | Switch / Sockets | As per inventory |
| 8.11 | Heating | As per inventory + Missing cap to right side radiator |
| 8.12 | Flooring | As per inventory + Few scratches and odd coloured marks |

Contents

| | | |
|------|----------|------------------|
| 8.13 | Sofa | As per inventory |
| 8.14 | Rug | As per inventory |
| 8.15 | Stool | As per inventory |
| 8.16 | WiFi box | As per inventory |

Cleanliness

| | | |
|------|-------------|----------------|
| 8.17 | Cleanliness | Domestic clean |
|------|-------------|----------------|



Ref #8.1



Ref #8.1




Ref #8.1

8. RECEPTION (CONT.)

| Ref | Name | Condition |
|---|-------------------|-----------|
|  | 03 Apr 2025 12:28 | Ref #8.3 |
|  | 03 Apr 2025 12:29 | Ref #8.4 |
|  | 03 Apr 2025 12:32 | Ref #8.5 |
|  | 03 Apr 2025 12:33 | Ref #8.3 |
|  | 03 Apr 2025 12:33 | Ref #8.5 |
|  | 03 Apr 2025 12:33 | Ref #8.5 |
|  | 03 Apr 2025 12:33 | Ref #8.5 |
|  | 03 Apr 2025 12:33 | Ref #8.5 |
|  | 03 Apr 2025 12:39 | Ref #8.6 |
|  | 03 Apr 2025 12:40 | Ref #8.6 |
|  | 03 Apr 2025 12:33 | Ref #8.7 |
|  | 03 Apr 2025 12:35 | Ref #8.8 |


8. RECEPTION (CONT.)

| Ref | Name | Condition |
|---|------|---|
|  | |  |
|  | |  |
|  | |  |
|  | |  |
|  | |  |
|  | |  |
|  | |  |
|  | |  |


8. RECEPTION (CONT.)

| Ref | Name | Condition |
|---|-------------------|---|
|  | |  |
| Ref #8.14 | 03 Apr 2025 12:41 | Ref #8.15 03 Apr 2025 12:42 |
| | |  |
| | | Ref #8.16 03 Apr 2025 12:43 |

9. INNER HALLWAY



Ref #9



Ref #9

| Ref | Name | Condition |
|-----|------------------|---|
| 9.1 | Ceiling | As per inventory |
| 9.2 | Lighting | As per inventory + All in good, working order |
| 9.3 | Walls | As per inventory + Brown mark to left wall on entry hallway Scattered scuff and few indents |
| 9.4 | Skirting | As per inventory + Appears faint brown spots and light marks |
| 9.5 | Switch / Sockets | As per inventory |
| 9.6 | Heating | As per inventory + Missing cap to right side |
| 9.7 | Flooring | As per inventory + Light brown stain marks and odd defect to centre |

Cleanliness

| | | |
|-----|-------------|----------------|
| 9.8 | Cleanliness | Domestic clean |
|-----|-------------|----------------|



Ref #9.1



Ref #9.3



Ref #9.3

9. INNER HALLWAY (CONT.)

| Ref | Name | Condition |
|---|------|---|
|  | |  |
|  | |  |
|  | |  |
|  | |  |
|  | |  |
|  | |  |


10. BATHROOM




Ref #10



Ref #10



Ref #10



Ref #10

| Ref | Name | Condition |
|------|-----------------|---|
| 10.1 | Door & Frame | As per inventory + Threshold is loose Few light marks and chips to door |
| 10.2 | Door Fixtures | As per inventory + Shaky levers |
| 10.3 | Ceiling | As per inventory |
| 10.4 | Extractor Fan | As per inventory + Clean and functional |
| 10.5 | Lighting | As per inventory + All lights are working |
| 10.6 | Walls | As per inventory |
| 10.7 | Windows & Sills | As per inventory + Few light marks to frame 1x window key seen Handle is loose Review - Investigate |

| 10. BATHROOM (CONT.) | | |
|----------------------|--------------------|---|
| Ref | Name | Condition |
| 10.8 | Switch / Sockets | As per inventory + Brown discolouration to end of cord |
| 10.9 | Heating | As per inventory + Light rust to panels |
| 10.10 | Flooring | As per inventory + Minor brown staining to grouting next to toilet |
| 10.11 | Built-In-Storage | As per inventory + Dust and debris to top of cabinet Good condition to interior |
| Bathroom Appliances | | |
| 10.12 | Toilet | As per inventory |
| 10.13 | Basin | As per inventory |
| 10.14 | Bath & Taps | As per inventory + Moderate tarnish to drain Appears to have been cleaned |
| Contents | | |
| 10.15 | Mirror | As per inventory + Silvering to base Tissue stuck to high level |
| 10.16 | Bin | As per inventory + Contents to interior |
| 10.17 | Toilet brush | As per inventory + Minor rust to lid Clean brush |
| 10.18 | Toilet roll holder | As per inventory + Loose to wall Review - Investigate |
| 10.19 | Mats | As per inventory |
| Cleanliness | | |
| 10.20 | Cleanliness | Domestic clean |


10. BATHROOM (CONT.)

| Ref | Name | Condition |
|---|------|---|
|  | |  |
|  | |  |
|  | |  |
|  | |  |
|  | |  |
|  | |  |
|  | |  |
|  | | |

10. BATHROOM (CONT.)

| Ref | Name | Condition |
|---|-------------------|------------|
|  | 03 Apr 2025 10:44 | Ref #10.8 |
|  | 03 Apr 2025 10:42 | Ref #10.9 |
|  | 03 Apr 2025 10:42 | Ref #10.10 |
|  | 03 Apr 2025 10:42 | Ref #10.10 |
|  | 03 Apr 2025 10:43 | Ref #10.11 |
|  | 03 Apr 2025 10:43 | Ref #10.11 |
|  | 03 Apr 2025 10:43 | Ref #10.11 |
|  | 03 Apr 2025 10:44 | Ref #10.11 |
|  | 03 Apr 2025 10:44 | Ref #10.11 |
|  | 03 Apr 2025 10:44 | Ref #10.11 |
|  | 03 Apr 2025 10:44 | Ref #10.12 |
|  | 03 Apr 2025 10:44 | Ref #10.12 |

10. BATHROOM (CONT.)

| Ref | Name | Condition |
|---|------|---|
|  | |  |
|  | | |
|  | |  |
|  | | |
|  | |  |
| | |  |
|  | |  |
| | |  |

10. BATHROOM (CONT.)

| Ref | Name | Condition |
|---|------------|---|
|  | |  |
| | |  |
| 03 Apr 2025 10:47 | Ref #10.17 | 03 Apr 2025 10:48 |
| 03 Apr 2025 10:49 | Ref #10.18 | Ref #10.19 |
|  | | |
| 03 Apr 2025 10:49 | Ref #10.19 | |

11. BEDROOM ONE




Ref #11



Ref #11



Ref #11



Ref #11

| Ref | Name | Condition |
|------|-----------------|--|
| 11.1 | Door & Frame | As per inventory + Minor brown mark to low left frame Few minor black marks to low level door |
| 11.2 | Door Fixtures | As per inventory + Exterior handle is loose Review - Investigate |
| 11.3 | Ceiling | As per inventory + Faint scuffs above right side wardrobe |
| 11.4 | Lighting | As per inventory + Good, working order |
| 11.5 | Walls | As per inventory + Moderate scuffs next to wardrobe Finger rub marks along bed |
| 11.6 | Skirting | As per inventory + Few light scuff or stain marks |
| 11.7 | Windows & Sills | As per inventory + Few light marks to left side of sill |

11. BEDROOM ONE (CONT.)

| Ref | Name | Condition |
|-------|-------------------|--|
| 11.8 | Blinds / Curtains | As per inventory + White paint marks to facing Moderate fraying to edges Some stains to reverse |
| 11.9 | Switch / Sockets | As per inventory + Appears light smearing to light switch Light marks to 1x socket |
| 11.10 | Heating | As per inventory |
| 11.11 | Flooring | As per inventory + Scrapes and scratches Slight wear to surface to right side |
| 11.12 | Built-In-Storage | As per inventory + Few light marks or chip defects Shelves stacked to right cabinet Mostly in clean condition |

Contents

| | | |
|-------|----------|---|
| 11.13 | Bed | As per inventory + Minor chip to edge of bed frame Light scuff to exterior of draw Clippings to edge of draw handle Mattress is clean |
| 11.14 | Doorstop | As per inventory + Secured |
| 11.15 | Fan | As per inventory |

Cleanliness

| | | |
|-------|-------------|--|
| 11.16 | Cleanliness | |
|-------|-------------|--|



Ref #11.1





Ref #11.1



Ref #11.1

11. BEDROOM ONE (CONT.)

| Ref | Name | Condition |
|---|-------------------|-----------|
|  | 03 Apr 2025 10:52 | Ref #11.2 |
|  | 03 Apr 2025 10:52 | Ref #11.3 |
|  | 03 Apr 2025 10:52 | Ref #11.3 |
|  | 03 Apr 2025 10:53 | Ref #11.3 |
|  | 03 Apr 2025 10:53 | Ref #11.3 |
|  | 03 Apr 2025 10:53 | Ref #11.4 |
|  | 03 Apr 2025 10:57 | Ref #11.5 |
|  | 03 Apr 2025 10:57 | Ref #11.5 |
|  | 03 Apr 2025 10:58 | Ref #11.6 |
|  | 03 Apr 2025 10:58 | Ref #11.6 |
|  | 03 Apr 2025 10:58 | Ref #11.6 |
|  | 03 Apr 2025 10:59 | Ref #11.7 |

| 11. BEDROOM ONE (CONT.) | | |
|---|------|---|
| Ref | Name | Condition |
|  | |  |
|  | | |
|  | | |
|  | | |
|  | |  |
|  | | |
|  | | |
|  | | |

| 11. BEDROOM ONE (CONT.) | | |
|---|------|---|
| Ref | Name | Condition |
|  | |  |
|  | |  |
|  | |  |
|  | |  |
|  | |  |
|  | |  |
|  | | |

11. BEDROOM ONE (CONT.)

| Ref | Name | Condition |
|---|-------------------|------------|
|  | 03 Apr 2025 11:05 | Ref #11.13 |
|  | 03 Apr 2025 11:05 | Ref #11.13 |
|  | 03 Apr 2025 11:05 | Ref #11.13 |
|  | 03 Apr 2025 11:05 | Ref #11.13 |
|  | 03 Apr 2025 11:05 | Ref #11.13 |
|  | 03 Apr 2025 11:06 | Ref #11.14 |
|  | 03 Apr 2025 11:06 | Ref #11.15 |


12. BEDROOM TWO




Ref #12



Ref #12



Ref #12



Ref #12

| Ref | Name | Condition |
|------|-----------------|--|
| 12.1 | Door & Frame | As per inventory + Faint brown shading to mid left frame Minor chip and shading to right side frame Chipping to base edge of door Faint scuff mark to door |
| 12.2 | Door Fixtures | As per inventory + Loose interior lever to backplate Review - Investigate |
| 12.3 | Ceiling | As per inventory |
| 12.4 | Lighting | As per inventory |
| 12.5 | Walls | As per inventory + Shading and scuff marks mid to low levels |
| 12.6 | Skirting | As per inventory |
| 12.7 | Windows & Sills | As per inventory + Light dust and marks to sill |

12. BEDROOM TWO (CONT.)

| Ref | Name | Condition |
|-------|-------------------|--|
| 12.8 | Blinds / Curtains | As per inventory + White paint mark to facing surface Fraying and creasing to edge Appears aged, functional |
| 12.9 | Switch / Sockets | As per inventory |
| 12.10 | Heating | As per inventory |
| 12.11 | Flooring | As per inventory + Moderate brown mark next to threshold Few white spots to right side Scratches and scuffs In clean condition |
| 12.12 | Built-In-Storage | As per inventory + Scuffs, chip or odd marks Faint rub marks to door edges Chrome pull loose to 1x unit door |

Contents

| | | |
|-------|-----------|-------------------------------|
| 12.13 | Container | As per inventory |
| 12.14 | Doorstop | As per inventory + Secured |

Cleanliness


| | | |
|-------|-------------|--------------------|
| 12.15 | Cleanliness | Professional clean |
|-------|-------------|--------------------|



Ref #12.1




Ref #12.1



Ref #12.1



Ref #12.1



Ref #12.1





Ref #12.3

12. BEDROOM TWO (CONT.)

| Ref | Name | Condition |
|---|-------------------|-----------|
|  | 03 Apr 2025 11:10 | Ref #12.4 |
|  | 03 Apr 2025 11:11 | Ref #12.5 |
|  | 03 Apr 2025 11:11 | Ref #12.5 |
|  | 03 Apr 2025 11:11 | Ref #12.5 |
|  | 03 Apr 2025 11:11 | Ref #12.5 |
|  | 03 Apr 2025 11:11 | Ref #12.5 |
|  | 03 Apr 2025 11:11 | Ref #12.5 |
|  | 03 Apr 2025 11:12 | Ref #12.7 |
|  | 03 Apr 2025 11:12 | Ref #12.7 |
|  | 03 Apr 2025 11:13 | Ref #12.7 |
|  | 03 Apr 2025 11:13 | Ref #12.7 |
|  | 03 Apr 2025 11:13 | Ref #12.8 |

12. BEDROOM TWO (CONT.)


| Ref | Name | Condition |
|---|------|---|
|  | |  |
|  | |  |
|  | |  |
|  | |  |
|  | |  |
|  | |  |
|  | |  |
|  | |  |

| 12. BEDROOM TWO (CONT.) | | |
|---|-------------------|------------|
| Ref | Name | Condition |
|  | 03 Apr 2025 11:17 | Ref #12.12 |
|  | 03 Apr 2025 11:17 | Ref #12.12 |
|  | 03 Apr 2025 11:18 | Ref #12.12 |
|  | 03 Apr 2025 11:19 | Ref #12.12 |
|  | 03 Apr 2025 11:19 | Ref #12.12 |
|  | 03 Apr 2025 11:20 | Ref #12.13 |
|  | 03 Apr 2025 11:20 | Ref #12.14 |


13. BEDROOM THREE




Ref #13



Ref #13



Ref #13



Ref #13

| Ref | Name | Condition |
|------|-------------------|---|
| 13.1 | Door & Frame | As per inventory + Light wear to threshold Few light marks or shading to framework Minor scuff, stain spot or indent to door |
| 13.2 | Door Fixtures | As per inventory |
| 13.3 | Ceiling | As per inventory |
| 13.4 | Lighting | As per inventory |
| 13.5 | Walls | As per inventory + Faint scuffing and shading Indent above 1x socket |
| 13.6 | Skirting | As per inventory + Few very faint marks Indent to angle |
| 13.7 | Windows & Sills | As per inventory |
| 13.8 | Blinds / Curtains | As per inventory + Minor stain spot and scratches to reverse of right side |

13. BEDROOM THREE (CONT.)

| Ref | Name | Condition |
|-------|------------------|---|
| 13.9 | Switch / Sockets | As per inventory |
| 13.10 | Heating | As per inventory |
| 13.11 | Flooring | As per inventory + Worn area to right side along skirting Moderate scratches and scrapes Gapping between some boards 1x board slightly sunken |

Contents

| | | |
|-------|---------------|--|
| 13.12 | Wardrobe | As per inventory + Minor white scratches to exterior |
| 13.13 | Bedside table | As per inventory + Loose pulls Few hair follicles to interior of draws |
| 13.14 | Side table | As per inventory + Lid not fitted and screwed on |
| 13.15 | Bed | As per inventory + Clean mattress |

Cleanliness

| | | |
|-------|-------------|----------------|
| 13.16 | Cleanliness | Domestic clean |
|-------|-------------|----------------|



Ref #13.1



Ref #13.1



Ref #13.1



Ref #13.1




Ref #13.1



Ref #13.1

13. BEDROOM THREE (CONT.)

| Ref | Name | Condition |
|--|-----------|---|
|  | |  |
| 03 Apr 2025 11:24 | Ref #13.1 | 03 Apr 2025 11:24 |
|  | |  |
| 03 Apr 2025 11:24 | Ref #13.1 | 03 Apr 2025 11:24 |
|  | |  |
| 03 Apr 2025 11:25 | Ref #13.1 | 03 Apr 2025 11:25 |
|  | |  |
| 03 Apr 2025 11:25 | Ref #13.3 | 03 Apr 2025 11:25 |
|  | |  |
| 03 Apr 2025 11:26 | Ref #13.4 | 03 Apr 2025 11:26 |
|  | |  |
| 03 Apr 2025 11:26 | Ref #13.5 | 03 Apr 2025 11:26 |
|  | |  |
| 03 Apr 2025 11:26 | Ref #13.5 | 03 Apr 2025 11:38 |

13. BEDROOM THREE (CONT.)

| Ref | Name | Condition |
|--|------------|---|
|  | |  |
| 03 Apr 2025 11:28 | Ref #13.6 | 03 Apr 2025 11:28 |
| 03 Apr 2025 11:28 | Ref #13.6 | 03 Apr 2025 11:28 |
|  | |  |
| Ref #13.7 | | Ref #13.7 |
| 03 Apr 2025 11:28 | Ref #13.7 | 03 Apr 2025 11:28 |
| 03 Apr 2025 11:28 | Ref #13.7 | 03 Apr 2025 11:28 |
|  | |  |
| Ref #13.7 | | Ref #13.8 |
| 03 Apr 2025 11:29 | Ref #13.8 | 03 Apr 2025 11:29 |
| 03 Apr 2025 11:29 | Ref #13.8 | 03 Apr 2025 11:29 |
|  | |  |
| 03 Apr 2025 11:31 | Ref #13.11 | 03 Apr 2025 11:31 |
| 03 Apr 2025 11:31 | Ref #13.11 | 03 Apr 2025 11:31 |
| 03 Apr 2025 11:31 | Ref #13.11 | 03 Apr 2025 11:31 |

13. BEDROOM THREE (CONT.)

| Ref | Name | Condition |
|---|------------|-------------------|
|  | | |
| | | 03 Apr 2025 11:31 |
| | Ref #13.11 | |
|  | | |
| | | 03 Apr 2025 11:31 |
| | Ref #13.11 | |
|  | | |
| | | 03 Apr 2025 11:31 |
| | Ref #13.11 | |
|  | | |
| | | 03 Apr 2025 11:32 |
| | Ref #13.11 | |
|  | | |
| | | 03 Apr 2025 11:32 |
| | Ref #13.11 | |
|  | | |
| | | 03 Apr 2025 11:32 |
| | Ref #13.11 | |
|  | | |
| | | 03 Apr 2025 11:32 |
| | Ref #13.11 | |
|  | | |
| | | 03 Apr 2025 11:34 |
| | Ref #13.12 | |
|  | | |
| | | 03 Apr 2025 11:37 |
| | Ref #13.12 | |
|  | | |
| | | 03 Apr 2025 11:37 |
| | Ref #13.12 | |
|  | | |
| | | 03 Apr 2025 11:37 |
| | Ref #13.12 | |
|  | | |
| | | 03 Apr 2025 11:35 |
| | Ref #13.13 | |


13. BEDROOM THREE (CONT.)

| Ref | Name | Condition |
|---|---------------------------------|---|
|  | |  |
| | |  |
| 03 Apr 2025 11:35 Ref #13.13 | 03 Apr 2025 11:36 Ref #13.13 | 03 Apr 2025 11:34 Ref #13.14 |
|  | |  |
| 03 Apr 2025 11:34 Ref #13.14 | 03 Apr 2025 11:34 Ref #13.14 |  |
| 03 Apr 2025 11:36 Ref #13.15 | | 03 Apr 2025 11:36 Ref #13.15 |
|  | | |
| 03 Apr 2025 11:36 Ref #13.15 | | |


14. EN-SUITE




Ref #14



Ref #14



Ref #14



Ref #14

| Ref | Name | Condition |
|------|-----------------|---|
| 14.1 | Door & Frame | As per inventory + Light surface chips to door |
| 14.2 | Door Fixtures | As per inventory + Levers slightly loose |
| 14.3 | Ceiling | As per inventory + Mould spotting above shower cubicle Review - Investigate |
| 14.4 | Extractor Fan | As per inventory + Appears dusty |
| 14.5 | Lighting | As per inventory + Good, working order |
| 14.6 | Walls | As per inventory + Exposed wall behind toilet Minor stain to grouting in shower unit Side panels appear detaching under basin |
| 14.7 | Windows & Sills | As per inventory + Light mould to frame and window panes Review - Investigate |

| 14. EN-SUITE (CONT.) | | |
|----------------------|------------------|---|
| Ref | Name | Condition |
| 14.8 | Switch / Sockets | As per inventory |
| 14.9 | Heating | As per inventory + Rusting to edges |
| 14.10 | Flooring | As per inventory + Chip to corner edge of 1x tile Aged stuck on debris |
| 14.11 | Built-In-Storage | Tall storage unit As per inventory + Rusting and chips Minor silvering to edge of mirror; Medicine cabinet As per inventory + Moderate ring marks and shading to interior |
| | | Review - Investigate |
| Bathroom Appliances | | |
| 14.12 | Toilet | As per inventory + Appears wear to interior Light dust or stain marks |
| 14.13 | Basin | As per inventory |
| 14.14 | Shower & Taps | As per inventory + Scaling to base of screen |
| Contents | | |
| 14.15 | Mirror | As per inventory + Slight silvering to edge Unable to operate lights |
| 14.16 | Bin | As per inventory |
| 14.17 | Toilet brush | As per inventory + Light discolouration |
| Cleanliness | | |
| 14.18 | Cleanliness | Domestic clean |


14. EN-SUITE (CONT.)

| Ref | Name | Condition |
|---|-------------------|-----------|
|  | 03 Apr 2025 11:40 | Ref #14.1 |
|  | 03 Apr 2025 11:41 | Ref #14.1 |
|  | 03 Apr 2025 11:41 | Ref #14.1 |
|  | 03 Apr 2025 11:41 | Ref #14.1 |
|  | 03 Apr 2025 11:41 | Ref #14.3 |
|  | 03 Apr 2025 11:41 | Ref #14.3 |
|  | 03 Apr 2025 11:41 | Ref #14.3 |
|  | 03 Apr 2025 11:42 | Ref #14.4 |
|  | 03 Apr 2025 11:42 | Ref #14.6 |
|  | 03 Apr 2025 11:43 | Ref #14.6 |
|  | 03 Apr 2025 11:52 | Ref #14.6 |
|  | 03 Apr 2025 11:43 | Ref #14.7 |

14. EN-SUITE (CONT.)

| Ref | Name | Condition |
|---|------|---|
|  | |  |
|  | |  |
|  | |  |
|  | |  |
|  | |  |
|  | |  |
|  | |  |
|  | | |

14. EN-SUITE (CONT.)

| Ref | Name | Condition |
|---|------|---|
|  | |  |
|  | |  |
|  | |  |
|  | |  |
|  | |  |
|  | |  |
|  | |  |

14. EN-SUITE (CONT.)

| Ref | Name | Condition |
|---|------------|---|
|  | |  |
| 03 Apr 2025 11:51 | Ref #14.14 | 03 Apr 2025 11:51 |
| 03 Apr 2025 11:51 | Ref #14.14 | 03 Apr 2025 11:51 |
|  | |  |
| Ref #14.15 | | 03 Apr 2025 11:51 |
| 03 Apr 2025 11:51 | Ref #14.15 | 03 Apr 2025 11:53 |
|  | |  |
| 03 Apr 2025 11:53 | Ref #14.16 | 03 Apr 2025 11:53 |
| 03 Apr 2025 11:53 | Ref #14.16 | Ref #14.17 |
|  | |  |
| Ref #14.17 | | 03 Apr 2025 11:53 |

15. GARDEN



Ref #15



Ref #15



Ref #15



Ref #15

| Ref | Name | Condition |
|------|------------------|--|
| 15.1 | Door and frame | As per inventory + Chip to base 1x key seen Glazing generally clean Door is functional |
| 15.2 | Description | Damage to brickwork |
| 15.3 | Outside lighting | As per inventory + Not working |

Contents

| | | |
|------|------|------------------|
| 15.4 | Shed | As per inventory |
| 15.5 | Mat | As per inventory |

Cleanliness

| | | |
|------|-------------|----------------|
| 15.6 | Cleanliness | Domestic clean |
|------|-------------|----------------|

15. GARDEN (CONT.)

| Ref | Name | Condition |
|---|------|---|
|  | |  |
|  | | |
|  | |  |
| | |  |
|  | |  |

| 16. PROPERTY COMPLIANCE | | | |
|-------------------------|----------------------------|--------|----------|
| Ref | Name | Answer | Comments |
| 16.1 | Is the Property Compliant? | Yes | |

| Actions Required | | | |
|---|-----------------|----------------|---|
| Ref | Action Required | Responsibility | Comments |
| 7.4 KITCHEN » Skirting | Review | Investigate | Brown staining next to fridge |
| 7.9 KITCHEN » Kitchen Units | Review | Investigate | Food debris to interior of draws |
| 7.14 KITCHEN » Oven & microwave | Review | Investigate | Moderate burnt on staining to baking tray |
| 8.8 RECEPTION » Windows & Sill | Review | Investigate | Orange drip staining under window |
| 8.9 RECEPTION » Blinds / Curtains | Review | Investigate | Moderate drip stains to right side curtain |
| 10.7 BATHROOM » Windows & Sills | Review | Investigate | Handle is loose |
| 10.18 BATHROOM » Toilet roll holder | Review | Investigate | Loose to wall |
| 11.2 BEDROOM ONE » Door Fixtures | Review | Investigate | Exterior handle is loose |
| 12.2 BEDROOM TWO » Door Fixtures | Review | Investigate | Loose interior lever to backplate |
| 14.3 EN-SUITE » Ceiling | Review | Investigate | Mould spotting above shower cubicle |
| 14.7 EN-SUITE » Windows & Sills | Review | Investigate | Light mould to frame and window panes |
| 14.11 EN-SUITE » Built-In-Storage | Review | Investigate | Moderate ring marks and shading to interior |

Declaration

I/We the undersigned, affirm that if I/we do not comment on the Inventory in writing within seven days of receipt of this Inventory then I/we accept the Inventory as being an accurate record of the contents and condition of the property.

Signed by the

Signatures

Print Name

Date / /

Signed by the

Signatures

Print Name

Date / /